HUI Powder Coat Technician Job Description

Completed By: Brenda Haese	Date: 2/13/2020	
Position is: Hourly	Reports To: Floor Supervisor	
Job Title: Powder Coat Technician	Direct Reports: N/A	
Department: Operations	Promotability/Progression: TBD	
Additional Roles: Cell Team Member		

Position Summary:

The Poweder Coat Technician is responsible for performing line load/unload and assembly, as well conducting quality checks to ensure parts meet all customer specifications.

Responsibilities:

- Loads and unloads parts from the overhead conveyor production line.
- Inspects for great quality to please the customer.
- Completes rework when necessary.
- Works as a teammate to complete customer orders.
- Powder coat and assemble quality parts.
- Problem solve effectively.
- Communicate with the team as a whole to get the day to day tasks done.
- Promote the HUI 5 work pillars.
- Safely run equipment with the proper PPE.
- Other duties as assigned.

Education/Training:

High School Diploma, GED or HSED required.

Knowledge/Skills/Abilities:

- Personal qualities of integrity, courage, respect, passion, growth and accountability.
- Experience working both independently and in a team-oriented, collaborative environment.
- Strong interpersonal and communication skills.
- Ability to effectively prioritize and execute tasks.
- Ability to stay organized in a fast-paced environment.
- Desire to take risks, be flexible, learn, and grow both personally and professionally.
- Ability to problem solve and implement new ideas.
- Open to receiving constructive feedback and willing to provide constructive feedback.

Working Environment:

• 100% - Manufacturing environment; clean, low to moderate noise, safety glasses and steel toes shoes required and other personal protective equipment where applicable.

	Never	Occasionally .25 – 2.5 Daily Hrs	Frequently 2.5 – 5.5 Daily Hrs	Continuously 5.5 – 8 Daily Hrs
Sit		X		
Stand				x
Lift Carry				
0-10 LBS			Х	
10-20 LBS			x	
20-50 LBS			х	
50-100 LBS		х		
Over 100 LBS	x			
Walk			X	
Drive		X		
Reach Above			Х	
Bend/Stoop			X	
Use hands for				
Pushing/Pulling			x	
Fine Manipulation			х	
Stress Level □ Low ☑ Moderate □ High □ Very High				